











Oxidation

CC518 • G-Mix 10







Reduction



Oxidation

CC512 • Three Finger Jack









Reduction





CC506 • Cookspride



CC518G • G-Mix 10 with Grog

 \odot \odot \odot \odot



CC512A • Three Finger Jack Architectural













CC517 • Crystal Springs Porcelain











CC502 • Mt Hood Porcelain











CC532 • Umpqua White













CC528 • Deschutes White









Key for Symbols:

When used for ...

Dinnerware Wheelthrowing Handbuilding Sculpture

Classroom Use

This clay is ...

= works OK

(3) = NOT recommended

Wadding Recipe for Firing

1 part Greenstripe Fireclay (CH379) + 1 part Coarse Grog (CH563)

2 parts Sand (CH354)

Blend dry ingredients, then mix with water to form a clay paste. Use Elmer's Glue to attach to the bottom of your greenware piece immediately before firing.