


Velvet Opaque Underglazes



Liquid Opaque Underglazes



Zinc-Free Clear Glaze



Zinc-Free Clear is a glossy glaze recommended for use with underglazes to reduce the incidence of color shift. Most underglazes, stains, and coloring oxides will show their best color with Zinc-Free Clear.

"Walleye" by
 Ron Korczynski,
 Natrona Heights, PA

